INTERNAL

Clear batch

PAX DEVICE CLEAR BATCH

If you need to reset PAX device, follow this instruction.

If you need to keep transactions, don't do this. This will erase everything in the device.

1. Press 1 + F
2. Enter Password (today's date, eg 10212019)
3. System Setting
4. Enter Password (today's date, eg 10212019)
5. Database
6. Clear Database
7. Hit OK